

ZED-PROG PACKS & APPLICATION LIST

| Pack Type | Module No | Vehicle & Immobiliser Unit Information | Eeprom Type | Description |
|--------------------------------|-----------|---|-----------------------|--|
| STANDART PACK (EEPROM PACK) | 3 | VW, Seat immo3 – Valeo immobox | 24C04 | Read Incircuit |
| | 4 | Fiat,Lancia,Citroen,Peugeot – Delphi immobox | 93C46 | Read Incircuit |
| | 6 | Honda, Acura – Megamos immobox | 93C46 | Read Incircuit |
| | 12 | Fiat, Citroen code2 – Delphi immobox | 93C56 | Read Incircuit |
| | 14 | Daihatsu 1998-2000 | 95C160 / 95C320 | Read with chip removal |
| | 15 | Daihatsu 2000-2001 | 93C66 | Read Incircuit |
| | 16 | Renault, Dacia – Sagem immobox | 93C46 | Read Incircuit |
| | 17 | Renault – Siemens UCH | 93C66 | Incircuit reading is not tested, chip removal is recommended |
| | 18 | Fiat, Lancia, Alfa Romeo – Delphi immobox | 93C66 | Read Incircuit |
| | 19 | Peugeot, Citroen – Valeo immobox | 93C46 | Read Incircuit |
| | 20 | Toyota Corolla 1998-99 – 89780-12060RI-3BTY | 93C66 | Read Incircuit |
| | 21 | Volvo immo3 – Bosch immobox | 93C56 | Read Incircuit |
| | 22 | Toyota Corolla – Bosch, Fujitsu ECU | 24C02 | Incircuit reading is not tested, chip removal is recommended |
| | 23 | Toyota Yaris 2 – Denso, Fujitsu ECU | 93C56 | Incircuit reading is not tested, chip removal is recommended |
| | 24 | Toyota – immobox | 24C04 | Read Incircuit |
| | 26 | Mercedes Actros, Atego – Temic immobox | 93C56 / 93C66 / 93C86 | Incircuit reading is not tested, chip removal is recommended |
| | 28 | Alfa Romeo Code2 – Bosch immobox | 93C56 | Incircuit reading is not tested, chip removal is recommended |
| | 29 | Mitsubishi – Bosch immobox | 93C56 | Incircuit reading is not tested, chip removal is recommended |
| | 33 | Iveco Daily, Iveco Truck – Bosch immobox | 93C56 | Incircuit reading is not tested, chip removal is recommended |
| | 34 | Renault – Valeo immobox | 93C46 | Incircuit reading is not tested, chip removal is recommended |
| | 35 | Alfa Romeo, Iveco – Bosch immobox | 93C46 | Incircuit reading is not tested, chip removal is recommended |
| | 36 | Suzuki Swift – Immobox | 93C66 | Incircuit reading is not tested, chip removal is recommended |
| | 37 | Toyota – ECU | 25080 / 95080 | Read Incircuit |
| | 38 | Volvo, Mitsubishi – Bosch immobox | 93C46 | Read Incircuit |
| | 39 | Toyota – Denso ECU | 93C56 | Incircuit reading is not tested, chip removal is recommended |
| | 42 | Renault Sagem UCH | 93C66 | Incircuit reading is not tested, chip removal is recommended |
| | 43 | Peugeot 406 – Siemens BSI | 93C66 | Incircuit reading is not tested, chip removal is recommended |
| | 45 | Audi – Delphi immobox | 93C46 | Incircuit reading is not tested, chip removal is recommended |
| | 46 | Peugeot, Fiat, Lancia, Citroen – Tecton immobox | 93C66 / 95040 | Incircuit reading is not tested, chip removal is recommended |
| | 47 | Chrysler, Dodge – SKIM immobox | 24C02 | Incircuit reading is not tested, chip removal is recommended |
| | 49 | Suzuki, Mitsubishi – immobox | 24C01 | Incircuit reading is not tested, chip removal is recommended |
| | 53 | Volvo – Bosch immobox | 93C46 | Incircuit reading is not tested, chip removal is recommended |
| | 55 | Opel, Isuzu – immobox | 93C46 | Incircuit reading is not tested, chip removal is recommended |
| | 57 | Fiat – Delphi BSI | 93C86 | Read Incircuit |
| | 62 | Ford – Visteon ECU | 95040 | Incircuit reading is not tested, chip removal is recommended |
| | 63 | Ford, Mazda – Siemens ECU | 93C56 | Incircuit reading is not tested, chip removal is recommended |
| | 67 | Honda, Acura – immobox | 93C46 | Incircuit reading is not tested, chip removal is recommended |
| | 69 | Yamaha bike – Moric immobox | S29190 | Read Incircuit |
| | 70 | Renault, Opel – Sagem UCH | 93C66 | Incircuit reading is not tested, chip removal is recommended |
| | 71 | Opel, Isuzu – immobox | 93C46 | Read Incircuit |
| | 72 | Suzuki – Denso immobox | 93C66 | Incircuit reading is not tested, chip removal is recommended |
| | 73 | Ducati bike – Magnetti Marelli Dashboard | 24C16 / 24C02 | Incircuit reading is not tested, chip removal is recommended |
| | 74 | Honda bike – immobox(93c46) | 93C46 | Incircuit reading is not tested, chip removal is recommended |
| | 75 | Honda bike – immobox(93c56) | 93C56 | Read Incircuit |
| | 76 | Honda bike – immobox(93c66) | 93C66 | Read Incircuit |
| | 77 | Renault Clio 3, Modus – Johnson UCH | 95160 | Incircuit reading is not tested, chip removal is recommended |
| | 78 | Aprilla Scooter bike – Dashboard | 24C01 / 24c16 | Incircuit reading is not tested, chip removal is recommended |
| | 79 | Mazda – Denso ECU | 93C56 | Incircuit reading is not tested, chip removal is recommended |
| | 80 | Mazda – Mitsubishi ECU | 24C01 | Incircuit reading is not tested, chip removal is recommended |
| | 81 | Peugeot Citroen - BSI | 95c160 | Incircuit reading is not tested, chip removal is recommended |
| | 83 | Ford – Delphi ECU | 95c160 | Incircuit reading is not tested, chip removal is recommended |
| | 87 | Hyundai – immobox | 93C56 | Incircuit reading is not tested, chip removal is recommended |
| | 88 | Ducati bike – Digitek Dashboard | 24C16 | Incircuit reading is not tested, chip removal is recommended |
| | 89 | Nissan – Dashboard | 93C66 | Incircuit reading is not tested, chip removal is recommended |

ZED-PROG PACKS & APPLICATION LIST

| Pack Type | Module No | Vehicle & Immobiliser Unit Information | Processor Mask | Description |
|-------------------------|---------------------------|--|--|--|
| PACK 1 (MC68HC0566) | 8 | Fiat, Lancia imm001.01 – magneti marelli immobox | F82B – G72G | To read incircuit, one line on the circuit board should be open circuited, details are described in the manual |
| | 50 | Peugeot, Fiat, Citroen – immobox | | To read incircuit, one line on the circuit board should be open circuited, details are described in the manual |
| | 51 | Toyota – immobox | | Read with chip removal(use reader clips) |
| | 85 | Toyota – Valeo immobox | | Will be added soon |
| PACK 2 (MC68HC11E99) | 30 | BMW, Range Rover, Mini Cooper – EWS1 | 0D46J – 1D47J – 2D47J | This processor should be read with chip removal, processors with mask number "2D47J" can not be read. |
| | 31 | BMW, Range Rover, Mini Cooper – EWS2 | | This processor should be read with chip removal, processors with mask number "2D47J" can not be read. |
| | 32 | BMW, Range Rover, Mini Cooper – EWS3 | | This processor can be read incircuit. Processors with mask number "2D47J" can not be read. |
| PACK 3 (MC68HC(7)05BXX) | 5 | Opel immo1 – Siemens immobox | B83T – B91T – D28J – D33J D54J – D59J – D60J – E50H F10V – F56K – G96A – G41V K20C | Read with chip removal(use reader clips) |
| | 7 | Honda, Rover – Valeo immobox | | Read with chip removal(use reader clips) |
| | 13 | VW,Skoda,Seat immo1 – Siemens immobox | | Read in circuit |
| | 40 | Nissan, Subaru – Siemens immobox | | Read with chip removal(use reader clips) |
| | 44 | Peugeot 206 – Siemens BSI | | Read with chip removal(use reader clips) |
| | 54 | Daewoo – immobox | | Read with chip removal(use reader clips) |
| | 56 | Renault – Siemens immobox | | Read with chip removal(use reader clips) |
| | 60 | Mazda – Lucas immobox | | Read with chip removal(use reader clips) |
| | 66 | Renault – Siemens UCH | | Read with chip removal(use reader clips) |
| 90 | Chevrolet – Siemens UCH | Will be added soon | | |
| PACK 4 (MC9S12DGXXX) | 11 | Fiat, Alfa Romeo, Lancia – magneti marelli immobox | 1K79X - 0L01Y | Read incircuit. See user manual for details. |
| | 25 | Renault Laguna 2 – Sagem UCH | | Will be added soon |
| | 27 | Renault Megane 2 – Siemens UCH | | Will be added soon |
| | 61 | Ford – Visteon Dashboard | | Will be added soon |
| | 65 | Fiat – Siemens BSI | | Will be added soon |
| | 68 | BMW, Range Rover,Mini Coper – EWS4 | | Will be added soon |
| PACK 5 (TMS) | 1 | Opel immo2 – Siemens immobox | TMS 28 Pin – TMS 44 Pin | Read with chip removal(use reader clips) |
| | 2 | VW, Seat immo2 – Siemens immobox | | Read with chip removal(use reader clips) |
| | 52 | Nissan – Siemens immobox(NATS-4) | | Will be added soon |
| | 58 | Ford – Pats box | | Read with chip removal(use reader clips) |
| | 59 | Ford – Pats box | | Read with chip removal(use reader clips) |
| PACK 6 (AZ32-05BX) | 9 | Fiat, Lancia imm110.01 - magneti marelli immobox | D60J – D62J – J66D – L72A | Read with chip removal(use reader clips) |
| | 10 | Mercedes Sprinter, Vito, Vw volt – Temic immobox | | Read with chip removal(use reader clips) |
| | 41 | Peugeot bike – Marelli immobox | | Read with chip removal(use reader clips) |
| | 47 | Chrysler, Dodge – SKIM immobox | | Read with chip removal(use reader clips) |
| | 64 | Fiat, Lancia – IMM100.01 Magnetti Marelli immobox | | Read with chip removal(use reader clips) |
| | 82 | Cherry – Immobox | | Will be added soon |
| 84 | Renault – Valeo BSI 98-02 | Will be added soon | | |